



Lake Baroon Catchment Care Group

Dairy Program Report

11 February 2021









• Bunding dimensions 100mm high x 375mm wide



- Calf rearing area to be upgraded
- Cork Family to contribute to project
- Site hardening and a effluent trap/transfer system









Protest Engineering 100mm test drill sites



- Seismic Testing
- Sunny day was required
- Site slashed prior by landholder
- Four Transects
- Six hours to complete
- Test indicating a flat bed











Arley Creek showing the effects of unrestricted livestock access





- Designated crossing constructed 1960's
- Site pugging by livestock Livestock water contaminated
- Poor ground cover

















